


## DER Repair Capabilities

CFM56-5B Fan Outlet Guide Vane  
(ATA72-23-03)



### Inner Platform Replacement Repair

- Salvage Repair
- 16-CCT-003-0

### Outer Platform Assembly Replacement Repair

- OEM Equivalent – Repair-010
- 02-CCT-009-1

### Solid Metal Leading Edge Replacement Repair

- OEM Equivalent – Repair-007
- 02-CCT-024-2

### Anti-Erosion Film (Tedlar®) Coating Replacement

Optional Addition of Airfoil Anti-Erosion Protection

- 03-CCT-037-1 (Polyurethane Coating)
- 05-CCT-005-1 (Tedlar® Film Coating)

Additional repairs for minor damage to salvage the Inner Platform rather than replace.

### Inner Platform Nicks, Dents, or Scratches Repair



- 05-CCT-001-1

### Inner Platform Mating Face and Width Repair

- 07-CCT-021-1

Chromalloy is continuously developing new FAA-approved technologies and repair solutions for engines. We strive to reduce costs and extend engine life with our industry leading repair solutions.

### Typical ID Platform Damage



### Corporate Office

3999 RCA Blvd.,  
Palm Beach Gardens, FL 33410

[chromalloy.com](http://chromalloy.com)