


# LifeX<sup>®</sup> Repairs

PW4000-94/100 Stage 2 HPT Ring Segment and Vane Cluster Assembly  
(55L492 / 55L582)



## New FAA Approved Repair - 19 CNY 06

**Engine:** PW4000 94" and 100" Series

**Manual:** Engine Manual PN 51A357


**Section:** 72-52-34 (Inspections & Repairs)

### Description:

Full repair capability for the second stage HPT vane including the latest configuration PN's 55L492 and 55L582 from P&W SB's 72-788 and 100-72-206.

This repair will blend Engine Manual and Chromalloy's proven, alternative repair procedures with an industry-first third time repair to provide an extended, additional FAA-approved source for HPT vane repairs.

*LifeX is Chromalloy's brand of customized aftermarket solutions that include parts, repairs, engine management, and serviceable materials that reduce the total cost of ownership of gas turbine engines. We partner closely with customers to understand immediate and long-term needs, and create unique, custom solutions to reduce engine down time, lower costs, and increase engine life.*



### Corporate Office

3999 RCA Blvd.,  
Palm Beach Gardens, FL 33410

[chromalloy.com](http://chromalloy.com)